



Radiography incident in Belgium




- Recovery of a Co-60 source in a foundry

Rutger Berden



Magotteaux Liège

Part of an international group




Metal casting company: grinding bodies, wear parts, industrial products.

Non destructive testing lab

Use of radioactive sources and X-ray equipment for quality control of pieces:

- Bunker 114 with 1 ^{60}Co HASS with nominal activity of 3,7 TBq in GammaMat TK 100 (current activity: 1,37 TBq)
- Bunker 113 with 1 ^{192}Ir HASS 1,5 TBq GammaMat TI (source depleted)
- Bunker 112 with 1 Balteau Baltographe TDS 320 (320 kV)


Control stations: room 109



Replacement of ^{60}Co source and container

1 September 2014:

- New licence for additional ^{60}Co HASS with nominal activity of 3,7 TBq in SENTRY 330 (QSA Global)
- Replacement for old GammaMat TK 100
- Use in bunker 114
- Storage of GammaMat TK100 with ^{60}Co (and GammaMat TI with depleted ^{192}Ir) in bunker 113 approved by inspection organisation





15 > 1 < 25	0 FE EN	W 12
25 > 1 < 32	0 FE EN	W 11
32 > 1 < 40	0 FE EN	W 10
40 > 1 < 55	0 FE EN	W 9
55 > 1 < 85	0 FE EN	W 8
85 > 1 < 150	1 FE EN	W 7
150 > 1 < 250	1 FE EN	W 6
		W 5
		W 4
Au dessus de 250		

8 > 1 < 12	0 FE EN	W 13
12 > 1 < 20	0 FE EN	W 12
20 > 1 < 30	0 FE EN	W 11
30 > 1 < 35	0 FE EN	W 10
35 > 1 < 45	0 FE EN	W 9
45 > 1 < 55	0 FE EN	W 8
55 > 1 < 120	1 FE EN	W 7
120 > 1 < 200	1 FE EN	W 6
		W 5
		W 4

100 > 1 < 150	1 FE EN	W 3
150 > 1 < 200	1 FE EN	W 2
200 > 1 < 250	1 FE EN	W 1







Automatic wind in/out

- ➔ Installation 15 January 2015
- ➔ Automated manipulation of the source



Friday 10 April 2015

- ✓ 10h30: source blocked outside the container
- ✓ No exposure of operators or public
 - ➔ security devices worked properly

First intervention to retrieve the source under supervision of certified organism and with the help of manufacturer with a camera and a long pole with a gripper.

- ➔ Ejection sheet unblocked, but source remained outside container.
- ✓ 15h22: Notification FANC



35 $\mu\text{Sv/h}$ →

350 $\mu\text{Sv/h}$ →



Monday 13 April 2015

Second intervention: similar to first but with new dome camera for better view.

- ➔ Cable unblocked and partially returned but source remained outside container.
- ➔ Further interventions not allowed by inspection organisation and FANC



What now?



Resolving issue

Synergie between

Exploiting company Magotteaux

Manufacturer NDT material: QSA Global
DOVO (part of Belgium National Defense)

Civil Protection

Federal Agency for Nuclear Control

Certified organism AIB Vinçotte Controlatom

Preparation phase

13 April - 11 May 2015

Action plan

- Need to establish a unique protocol to retrieve the source: directed by Magotteaux and Controlatom
 - ➔ Approved by FANC
- Use of military grade robot, used for mine clearing purposes
- Renting of storage container Sentinel QSA 680 from Applus RTD (Netherlands)
- Cold test on real size mock-up of irradiation vault

15/04/2015

Town hall Chaudfontaine

Information sharing

Mayor Chaudfontaine, Police Chaudfontaine, Fire Department Chaudfontaine, Belgian Defence, Civil Protection, DOVO, AVC, Magotteaux, FANC

- Description of incident.
- No risk to public or workers.

Incident provisionally scaled as INES 1

16/04/2015

Magotteaux factory

Information sharing and discussion of open questions

Belgian Defence, Civil Protection, DOVO, AVC, FANC, QSA, Magotteaux

- No damage to source (no contamination)
- Source can be pushed out, not retracted
- Possibility of deployment of robot?
- Performance of robot?
- Compatibility of material?

Testing

12 May 2015

Robot moving the container that will house the source

-


Undercarriage fabricated for source retrieval


-

Tests showed that undercarriage needed to be modified









Test source entered in
container

–

safely interlocked

–

success of the test





Intervention

12 May 2015




Preparation of
retrieval

–


Robot entering
the irradiation
vault









10.6X










35 mSv

CAUSE:

**Preliminary risk assessment
&
human error**









Operations to put installation back into service 12 – 18 May 2015

1. Complete maintenance of SENTRY 330 container (certificate QSA)
2. Replacement of drive cable
3. Use of new one piece ejection sheets with lock on the SENTRY 330 container
4. Extensive cold tests
5. Coupling of source holder on new cable and reintegration of source in SENTRY 330

Installation in service

18 May 2015

- Testing of security devices.
- Approval of new work procedure
- Completion of incident report

By certified organism

- Confirmation INES 1 (29/05/2015)

By FANC

Dosimetry

All intervenants present during the source retrieval wore an OSL dosimeter provided by AVC



All read-outs were below threshold.

Costs

	Cost (€)
Interventions external counterparts	
Controlatom, QSA, Army	42.000
FANC	FREE
Internal service	
IT, general building service (construction mock-up bunker, and scaffolding), maintenance personnel	10.000
Extra equipment	
Caméras , scaffoldings, long tongs, mock-up bunker,...	5.000
Immobilisation of industrial gammagraphy for 1 month	8.000
Total	65.000

Questions